

Figure 1 (Prior Art)







FIGURE 2A








502h 5024 5024 502h 50 Za 502e 5029 Adaptec's Fibre Channel Failover Software: 504c. Information Configuration Cink Status (IO Status 5046 AFC9100-Port3

AFC9100-Port4 AFC9100-Port3 504c Controller To the Rot D Vendor ID DOYMORD OLDEDI Product ID Revision Drive Letter 0147,65001,0000005 00478500100d005


F15 5



F19 6A

600b

608




504a

FIS GB


700a


70Z



5046


Fig 7A





FIS 7B





1.8

710 Adaptec's Fibre Channel Failover. Software: Information Configuration LinkStatus 10 Status AFC9100-Port3 26025 602 24715 32341 7740 2398 ST318275FCPort4Target0Lun0 ST318275FCPort4Target1Lun0 ST318275FCPort4Target3Lun0 AFC9100-Port3

D- AFC9100-Port4 Select one or more devices to watch 10 status 4 504d

F13 9